


## Automobilista 1, 2 & 2 Beta not detecting wheel inputs

I've recently rebuilt & upgraded my computer and upon installation of Automobilista 1 & 2 I cannot get the software to recognise my SimSteering wheel Left & Right steering and my Heusinkveld Pedal inputs.


The game minimises to the task bar after I get the main menu screen. The second screen changes as well – see screen shots below:




Screen shot shown above is when game starts then within a few seconds the screen changes to what you see below.



## Automobilista 1, 2 & 2 Beta not detecting wheel inputs




The screen shot above is the second screen when the game starts.



“Controls Inputs” Screen Shot – no device detected

## Automobilista 1, 2 & 2 Beta not detecting wheel inputs



“Controls Settings” Screen Shot – no device detected

### System Information:

- i7 9700K Intel CPU,
- 1TB M.2 2280 NVMe SSD,
- Gigabyte Z390 Gaming X M/B,
- 16Gb DDR4 Ram,
- MSI Geforce RTX2080Ti Graphics Card,
- DirectX 12
- Steam Account

### Gaming Information:

- Leo Bodnar Simsteering 2 (54) direct drive wheel
- Heusinkveld Ultimate Pro Pedals
- Heusinkveld GT Gaming Rig
- 3 x 27" Asus VE278 Monitors – 5760 x 1080 @ 60Hz resolution
- Automobilista v1.5.3 hotfix deployed

Can anyone suggest some possible fixes? Please information files attached.